

NPA - PREVIEW ALL UNITS

ITEM# 2147 2002 SUZUKI DL1000K2 V-STROM











	VEHICLE DETAILS
Item #	2147
Year	2002
Make	SUZUKI
Model	DL1000K2 V-STROM
VIN	JS1VT53A822100850
Color	BLUE
Miles / Hours	TMU
Documents	TX TITLE
Location	Dallas
Clean Wholesale	\$1,335
Vehicle Auction Notes	TMU-GAUGES INOP

CONDITION REPORT = 75	(Total) 85	(Mechanical)	/ 69	(Cosmetic)	

CONDITION REPORT

ENGINE - MECHANICAL	9	OPERATES NORMAL - EXHAUST LEAK
TRANSMISSION	9	OPERATES NORMAL
FRAME	8	COSMETIC LIGHT
ENGINE/TRANSMISSION COSMETIC	7	COSMETIC HEAVY - COVER SCRATCHES

FAIRING/LEFT	7	COSMETIC HEAVY - SCRATCHES		
FAIRING/RIGHT	7	COSMETIC HEAVY - SCRATCHES		
FAIRING/UPPER	7	COSMETIC HEAVY - SCRATCHES		
FUEL TANK	5	COSMETIC DAMAGE - DENTED, DINGED, CHIPS, SCRATCHES		100
LUGGAGE	-	Not Rated		
SUSPENSION/FRONT	7	SEAL LEAK		
SUSPENSION/REAR	7	COSMETIC HEAVY - SCRATCHED		
REVERSE	-	Not Rated		
EXHAUST SYSTEM	5	COSMETIC DAMAGE - SHIELDING DENTS UNDERNEATH LUGGAGE	September 1	
TAIL PIECE	8	COSMETIC LIGHT		
STEERING	8	COSMETIC LIGHT	ě.	
WHEEL/FRONT	7	COSMETIC HEAVY - SCRATCHES		
WHEEL/REAR	7	COSMETIC HEAVY - SCRATCHES		
SHOCK(S)/REAR	8	COSMETIC LIGHT	P	21
CONTROLS/FOOT	6	SOME PARTS BENT - BRAKE PEDAL	Y	
CONTROLS/HAND	5	COSMETIC DAMAGE - BRUSH GUARD CRACKED, SCRATCHES		
FUEL TANK COVER/TRIM PIECES	8	COSMETIC LIGHT		
BRAKES/FRONT	8	LIGHT WEAR		Asia.

BRAKES/REAR	8	LIGHT WEAR	
TIRE/FRONT - SPORT	9	4/32 AND UP	
TIRE/REAR - SPORT	9	5/32 AND UP	36.
FINAL DRIVE	8	LIGHT WEAR	
FOOT RESTS	7	HEAVY WEAR - SCRATCHES	
GAUGES/ODOMETER	4	INOP - DISPLAYS AND MPH, RPM NOT FUNCTIONING	
LIGHTS	8	COSMETIC LIGHT	1
SEAT(S)	5	RIPPED/CRACKED	
FENDER/FRONT	7	COSMETIC HEAVY - SCRATCHES	5 Nr. C
ELECTRONICS	-	Not Rated	
MIRRORS	7	COSMETIC HEAVY - SCRATCHES	WOR.
TURN SIGNALS	5	COSMETIC DAMAGE - REAR SIGNALS CRACKED AT POSTS	P
WINDSHIELD	7	COSMETIC HEAVY - SCRATCHES	
BATTERY	9	BATTERY WORKS	
STAND	7	HEAVY WEAR - SCRATCHES	
FENDER/REAR	9	GOOD	
IGNITION SWITCH	9	OPERATIONAL/HAS KEY	
STARTS/RUNS	9	YES	and the same of the same



