


NPA - PREVIEW ALL UNITS

ITEM# 1133 2012 SUZUKI M109R BOULEVARD





	VEHICLE DETAILS
Item #	1133
Year	2012
Make	SUZUKI
Model	M109R BOULEVARD
VIN	JS1VY53AXC2100366
Color	BLACK
Miles / Hours	10439
Documents	TX TITLE
Location	Dallas
Clean Wholesale	\$5,210
Vehicle Auction Notes	N/A

CONDITION REPORT							
CONDITION REPORT = 73 (Total) 80 (Mechanical) / 70 (Cosmetic)							
7	RUNS ROUGH						
7	COSMETIC HEAVY - HEAVY SCRATCHES						
9	OPERATES NORMAL						
8	COSMETIC LIGHT						
7	COSMETIC HEAVY - SCRATCHES						
7	COSMETIC HEAVY - SCRATCHES, CHIPPED						
7	COSMETIC HEAVY						
7	COSMETIC HEAVY - SCRATCHES						
8	COSMETIC LIGHT						
8	COSMETIC LIGHT						
7	COSMETIC HEAVY - SCRATCHES						
7	COSMETIC HEAVY - SCRATCHES						
-	Not Rated						
-	Not Rated						
5	COSMETIC DAMAGE - MULTIPLE DENTS						
8	LIGHT WEAR						
7	COSMETIC HEAVY - SCRATCHES						
8	COSMETIC LIGHT						
5	COSMETIC DAMAGE - BRAKE PEDAL SCRAPED AND BENT						
7	HEAVY WEAR - SCRATCHES						
8	COSMETIC LIGHT						
5	COSMETIC DAMAGE - SCRAPED						
	7 7 9 8 7 7 7 8 8 7 7 5 8 7 8 8 7						

STEERING	7	CLAMPS MISALIGNED/TWISTED	
BRAKES/FRONT	8	LIGHT WEAR	
BRAKES/REAR	8	LIGHT WEAR	
WINDSHIELD	-	Not Rated	11/
ELECTRONICS	-	Not Rated	to I
SIDE COVERS	7	COSMETIC HEAVY - SCRATCHES	
TIRE/FRONT - CRUISER	9	4/32 AND UP	2
TIRE/REAR - CRUISER	9	5/32 AND UP	5
FOOT RESTS	7	HEAVY WEAR	
GAUGES/ODOMETER	9	GOOD	
GAUGES/OIL/VOLT	-	Not Rated	
LIGHTS	5	COSMETIC DAMAGE - HEADLIGHT COVER CRACKED	
SEAT(S)	8	LIGHT WEAR	
MIRRORS	8	COSMETIC LIGHT	
TURN SIGNALS	5	COSMETIC DAMAGE - FRONT RIGHT COSMETIC DAMAGE	
BATTERY	9	BATTERY WORKS	
IGNITION SWITCH	9	OPERATIONAL/HAS KEY	
STAND	8	LIGHT WEAR	
STARTS/RUNS	9	YES	

