


NPA - PREVIEW ALL UNITS

ITEM# 1053

2009 YAMAHA XVS13CTYL/C V-STAR TOUR



VEHICLE DETAILS	
Item #	1053
Year	2009
Make	YAMAHA
Model	XVS13CTYL/C V-STAR TOUR
VIN	JYAVP25E59A008731
Color	BLU/SLV
Miles / Hours	10866
Documents	AZ TITLE
Location	Cincinnati
Clean Wholesale	\$2,965
Vehicle Auction Notes	N/A

CONDITION REPORT		
CONDITION REPORT = 74 (Total)		
ENGINE MECHANICAL	9	RUNS GOOD/NORMAL
FRAME MOTORCYCLE	8	COSMETIC BOTTOM FRAME
TRANSMISSION M/C	9	GOOD/SHIFTS OPERATES NORMAL
ENGINE COSMETIC	8	COSMETIC LIGHT
FUEL TANK M/C	7	COSMETIC HEAVY - OVERSPRAY
FAIRING/UPPER	-	Not Rated
SUSPENSION/FRONT	7	COSMETIC HEAVY
SUSPENSION/REAR	7	COSMETIC HEAVY
LUGGAGE	5	COSMETIC DAMAGE
FENDER/FRONT	7	COSMETIC HEAVY - OVERSPRAY
FENDER/REAR	8	COSMETIC LIGHT
FAIRING/LEFT	-	Not Rated
FAIRING/RIGHT	-	Not Rated
FINAL DRIVE	8	COSMETIC LIGHT
EXHAUST M/C	5	MODIFIED
WHEEL/FRONT MC	7	COSMETIC HEAVY
WHEEL/REAR MC	7	COSMETIC HEAVY
CONTROLS/HAND	7	COSMETIC HEAVY - RESERVOIR CORRODED / AFTERMARKET BARS AND GRIPS
STEERING M/C	7	COSMETIC HEAVY
FUEL TANK COVER/SHROUDS	-	Not Rated
CONTROLS/FOOT	7	COSMETIC HEAVY
BRAKES/FRONT	8	COSMETIC LIGHT
BRAKES/REAR	7	COSMETIC HEAVY
WINDSHIELD MC	0	MISSING



SIDE COVERS M/C	7	COSMETIC HEAVY
TIRE/FRONT CRUISER	1	POOR/AT WEAR LINE OR LESS
TIRE/REAR CRUISER	9	5/32 AND UP
ELECTRONICS	-	Not Rated
GAUGES/OIL/VOLT	-	Not Rated
LIGHTS M/C	8	COSMETIC LIGHT
SEAT M/C	7	STAINED/FADED
GAUGES ODO M/C	8	COSMETIC LIGHT
FOOT RESTS	7	COSMETIC HEAVY
MIRRORS	8	COSMETIC LIGHT
TURN SIGNALS	8	COSMETIC LIGHT
STAND	8	COSMETIC LIGHT
IGNITION SWITCH	9	GOOD
BATTERY	9	BATTERY WORKS