


NPA - PREVIEW ALL UNITS

ITEM# 1045

2011 HONDA VT13CTB INTERSTATE




VEHICLE DETAILS

Item #	1045
Year	2011
Make	HONDA
Model	VT13CTB INTERSTATE
VIN	JH2SC6678BK100420
Color	BLK
Miles / Hours	16678
Documents	MD TITLE
Location	Cincinnati
Clean Wholesale	\$4,510
Vehicle Auction Notes	N/A

CONDITION REPORT

ENGINE MECHANICAL	9	RUNS GOOD/NORMAL
FRAME MOTORCYCLE	6	COSMETIC DAMAGE
TRANSMISSION M/C	9	GOOD/SHIFTS OPERATES NORMAL
ENGINE COSMETIC	7	COSMETIC HEAVY
FUEL TANK M/C	6	DENTED
FAIRING/UPPER	-	Not Rated
SUSPENSION/FRONT	7	COSMETIC HEAVY
SUSPENSION/REAR	9	GOOD
LUGGAGE	5	COSMETIC DAMAGE
FENDER/FRONT	5	COSMETIC DAMAGE
FENDER/REAR	5	COSMETIC DAMAGE
FAIRING/LEFT	-	Not Rated
FAIRING/RIGHT	-	Not Rated
FINAL DRIVE	8	COSMETIC LIGHT
EXHAUST M/C	5	COSMETIC DAMAGE - AFTERMARKET
WHEEL/FRONT MC	8	COSMETIC LIGHT
WHEEL/REAR MC	8	COSMETIC LIGHT
CONTROLS/HAND	9	GOOD
STEERING M/C	7	COSMETIC HEAVY
FUEL TANK COVER/SHROUDS	9	GOOD
CONTROLS/FOOT	7	SHIFT LEVER BENT
BRAKES/FRONT	7	COSMETIC HEAVY
BRAKES/REAR	5	SOME PARTS DAMAGED OR WORN - ROTOR GROOVED
WINDSHIELD MC	-	Not Rated
SIDE COVERS M/C	7	COSMETIC HEAVY
TIRE/FRONT CRUISER	7	NORMAL WEAR 4/32 TO 3/32
TIRE/REAR CRUISER	4	WORN 2/32 OR 1/32
ELECTRONICS	-	Not Rated



GAUGES/OIL/VOLT	-	Not Rated
LIGHTS M/C	8	COSMETIC LIGHT
SEAT M/C	9	GOOD - AFTERMARKET
GAUGES ODO M/C	9	GOOD
FOOT RESTS	6	COSMETIC DAMAGE - RIDER LEFT
MIRRORS	8	COSMETIC LIGHT
TURN SIGNALS	8	COSMETIC LIGHT
STAND	8	COSMETIC LIGHT
IGNITION SWITCH	9	GOOD
BATTERY	9	BATTERY WORKS