


**NPA - PREVIEW ALL UNITS**

**ITEM# 1127**  
**2006 SUZUKI M109RK6**



**VEHICLE DETAILS**

Item #	1127
Year	2006
Make	SUZUKI
Model	M109RK6
VIN	JS1VY53A562102854
Color	SLVR
Miles / Hours	33302
Documents	AL TITLE
Location	Atlanta
Clean Wholesale	\$4,180
Vehicle Auction Notes	MILEAGE EXEMPT ON TITLE

**CONDITION REPORT**

CONDITION REPORT = 68 (Total) 65 (Mechanical) / 66 (Cosmetic)

ENGINE - MECHANICAL	9	OPERATES NORMAL
FRAME - CRUISER	5	COSMETIC DAMAGE - BOTTOM RAIL DENTED
TRANSMISSION	5	MECHANICAL ISSUE - NOISY CLUTCH
ENGINE/TRANSMISSION COSMETIC	7	COSMETIC HEAVY - BOTTOM GOUGED
FAIRING/UPPER	7	COSMETIC HEAVY - SCRATCHED
FUEL TANK	7	COSMETIC HEAVY - SCRATCHED
SUSPENSION/FRONT	7	SEAL LEAK
SUSPENSION/REAR	7	COSMETIC HEAVY - SCRATCHED
FAIRING/LEFT	7	COSMETIC HEAVY - CHIPS, SCRATCHED
FAIRING/RIGHT	5	COSMETIC DAMAGE - CHIPS, GOUGED
FENDER/FRONT	7	COSMETIC HEAVY - CHIPS
FENDER/REAR	7	COSMETIC HEAVY - CHIPS
LUGGAGE	-	Not Rated
REVERSE	-	Not Rated
EXHAUST SYSTEM	5	COSMETIC DAMAGE - DENTED , LOOSE HARDWARE
FINAL DRIVE	7	HEAVY WEAR - CHIPS
WHEEL(S)/FRONT	7	COSMETIC HEAVY - CHIPS
WHEEL(S)/REAR	7	COSMETIC HEAVY - CHIPS
CONTROLS/FOOT	7	HEAVY WEAR
CONTROLS/HAND	7	HEAVY WEAR - CORROSION

FUEL TANK COVER/TRIM PIECES	8	COSMETIC LIGHT
SHOCK(S)/REAR	7	COSMETIC HEAVY - CORROSION
STEERING	7	COSMETIC HEAVY - SCRATCHED
BRAKES/FRONT	4	INOPERABLE/UNSAFE - COATED IN OIL
BRAKES/REAR	7	HEAVY WEAR - BLUEING
WINDSHIELD	-	Not Rated
ELECTRONICS	-	Not Rated
SIDE COVERS	7	COSMETIC HEAVY - SCRATCHED
TIRE/FRONT - CRUISER	1	CRACKED
TIRE/REAR - CRUISER	2	2/32 OR LESS
FOOT RESTS	5	COSMETIC DAMAGE - SCRAPED
GAUGES/ODOMETER	8	COSMETIC LIGHT
GAUGES/OIL/VOLT	-	Not Rated
LIGHTS	7	COSMETIC HEAVY - SCRATCHED, AFTERMARKET COMPONENTS
SEAT(S)	7	STAINED/FADED - CHIPPED COWL , OVERSPRAY
MIRRORS	7	COSMETIC HEAVY - AFTERMARKET, CORROSION
TURN SIGNALS	8	COSMETIC LIGHT
BATTERY	9	BATTERY WORKS
IGNITION SWITCH	9	OPERATIONAL/HAS KEY
STAND	8	LIGHT WEAR
STARTS/RUNS	9	YES

