


NPA - PREVIEW ALL UNITS

ITEM# 1309

2008 SUZUKI M109RK8 BOULEVARD



	VEHICLE DETAILS
Item #	1309
Year	2008
Make	SUZUKI
Model	M109RK8 BOULEVARD
VIN	JS1VY53A682101974
Color	BLACK
Miles / Hours	18512
Documents	TX TITLE
Location	Dallas
Clean Wholesale	\$4,720
Vehicle Auction Notes	MILEAGE EXEMPT ON TITLE

CONDITION REPORT

ENGINE - MECHANICAL	9	OPERATES NORMAL	
FRAME - CRUISER		COSMETIC BOTTOM FRAME	
TRANSMISSION	5	MECHANICAL ISSUE	
ENGINE/TRANSMISSION COSMETIC	8	COSMETIC LIGHT	
FAIRING/UPPER	5	COSMETIC DAMAGE - GOUGED	
FUEL TANK	5	COSMETIC DAMAGE - DENTED	
SUSPENSION/FRONT	8	COSMETIC LIGHT	
SUSPENSION/REAR	8	COSMETIC LIGHT	
FAIRING/LEFT	7	COSMETIC HEAVY - BOTTOM SCRATCHED	
FAIRING/RIGHT	8	COSMETIC LIGHT	
FENDER/FRONT	5	COSMETIC DAMAGE - HEAVILY SCRAPED	
FENDER/REAR	5	COSMETIC DAMAGE - DENTED WITH SCRAPES	
LUGGAGE	-	Not Rated	
REVERSE	-	Not Rated	
EXHAUST SYSTEM	8	COSMETIC LIGHT	
FINAL DRIVE	8	LIGHT WEAR	
WHEEL(S)/FRONT	7	COSMETIC HEAVY - CHIPS	
WHEEL(S)/REAR	8	COSMETIC LIGHT	
CONTROLS/FOOT	6	SOME PARTS BENT - BRAKE PEDAL BENT	
CONTROLS/HAND	7	HEAVY WEAR - BARS SCRATCHED	
FUEL TANK COVER/TRIM PIECES	8	COSMETIC LIGHT	
SHOCK(S)/REAR	8	COSMETIC LIGHT	
STEERING	8	COSMETIC LIGHT	
BRAKES/FRONT	8	LIGHT WEAR	

BRAKES/REAR	8	LIGHT WEAR		MART
WINDSHIELD	-	Not Rated	\geq	
ELECTRONICS	-	Not Rated	10	
SIDE COVERS	7	COSMETIC HEAVY		1
TIRE/FRONT - CRUISER	7	4/32 TO 3/32	autil 1	RASS
TIRE/REAR - CRUISER	7	3/32 TO 5/32	1	A Deep
FOOT RESTS	8	LIGHT WEAR		
GAUGES/ODOMETER	8	COSMETIC LIGHT	1	
GAUGES/OIL/VOLT	-	Not Rated		
LIGHTS	5	COSMETIC DAMAGE - SCRAPED	田田	
SEAT(S)	8	LIGHT WEAR		
MIRRORS	7	COSMETIC HEAVY		
TURN SIGNALS	5	COSMETIC DAMAGE - SCRAPED DOWN		
BATTERY	9	BATTERY WORKS		
IGNITION SWITCH	9	OPERATIONAL/HAS KEY		
STAND	8	LIGHT WEAR		
STARTS/RUNS	9	YES		

