


NPA - PREVIEW ALL UNITS

ITEM# 1336

2004 SUZUKI VL800BK4 INTRUDER VOLUSIA



VEHICLE DETAILS

Item #	1336
Year	2004
Make	SUZUKI
Model	VL800BK4 INTRUDER VOLUSIA
VIN	JS1VS54A242101609
Color	SILVER/BLUE
Miles / Hours	24483
Documents	TX TITLE
Location	Dallas
Clean Wholesale	\$1,275
Vehicle Auction Notes	MILEAGE EXEMPT ON TITLE

CONDITION REPORT

CONDITION REPORT = 75 (Total) 80 (Mechanical) / 73 (Cosmetic)

ENGINE - MECHANICAL	9	OPERATES NORMAL
FRAME - CRUISER	7	COSMETIC HEAVY - BOTTOM SCRAPED
TRANSMISSION	9	OPERATES NORMAL
ENGINE/TRANSMISSION COSMETIC	8	COSMETIC LIGHT
FAIRING/UPPER	-	Not Rated
FUEL TANK	5	COSMETIC DAMAGE - DENTED
SUSPENSION/FRONT	7	COSMETIC HEAVY - CORROSION
SUSPENSION/REAR	8	COSMETIC LIGHT
FAIRING/LEFT	-	Not Rated
FAIRING/RIGHT	-	Not Rated
FENDER/FRONT	7	COSMETIC HEAVY - HEAVY SCRATCHES
FENDER/REAR	7	COSMETIC HEAVY - SCRATCHED
LUGGAGE	-	Not Rated
REVERSE	-	Not Rated
EXHAUST SYSTEM	7	COSMETIC HEAVY
FINAL DRIVE	8	LIGHT WEAR
WHEEL(S)/FRONT	8	COSMETIC LIGHT
WHEEL(S)/REAR	8	COSMETIC LIGHT
CONTROLS/FOOT	8	LIGHT WEAR
CONTROLS/HAND	7	HEAVY WEAR - GRIPS WORN
FUEL TANK COVER/TRIM PIECES	8	COSMETIC LIGHT
SHOCK(S)/REAR	8	COSMETIC LIGHT
STEERING	8	COSMETIC LIGHT
BRAKES/FRONT	8	LIGHT WEAR
BRAKES/REAR	8	LIGHT WEAR

WINDSHIELD	-	Not Rated
ELECTRONICS	-	Not Rated
SIDE COVERS	7	COSMETIC HEAVY
TIRE/FRONT - CRUISER	2	2/32 OR LESS
TIRE/REAR - CRUISER	2	2/32 OR LESS
FOOT RESTS	8	LIGHT WEAR
GAUGES/ODOMETER	8	COSMETIC LIGHT
GAUGES/OIL/VOLT	-	Not Rated
LIGHTS	8	COSMETIC LIGHT
SEAT(S)	7	STAINED/FADED
MIRRORS	7	COSMETIC HEAVY
TURN SIGNALS	8	COSMETIC LIGHT
BATTERY	9	BATTERY WORKS
IGNITION SWITCH	9	OPERATIONAL/HAS KEY
STAND	8	LIGHT WEAR
STARTS/RUNS	9	YES

