


**NPA - PREVIEW ALL UNITS**

**ITEM# 1021**

**2004 YAMAHA XVZ13TFS/C RYL STR VNTR**











**VEHICLE DETAILS**











|                       |                         |
|-----------------------|-------------------------|
| Item #                | 1021                    |
| Year                  | 2004                    |
| Make                  | YAMAHA                  |
| Model                 | XVZ13TFS/C RYL STR VNTR |
| VIN                   | JYAVP04E14A007672       |
| Color                 | WHITE                   |
| Miles / Hours         | 28394                   |
| Documents             | LA TITLE                |
| Location              | Dallas                  |
| Clean Wholesale       | \$4,105                 |
| Vehicle Auction Notes | N/A                     |

**CONDITION REPORT**

CONDITION REPORT = 67 (Total) 72 (Mechanical) / 64 (Cosmetic)

|                     |   |   |
|---------------------|---|---|
| ENGINE - MECHANICAL | 7 | VERIFIED<br>RUNNABLE/REPAIRS<br>REQUIRED          |
| FRAME - CRUISER     | 7 | FRAME TAB BENT -<br>BOTTOM TAB BENT,<br>SCRATCHES |
| TRANSMISSION        | 9 | OPERATES NORMAL -<br>TECHNICIAN VERIFIED          |

|                                     |   |   |  |
|-------------------------------------|---|---|--|
| <b>ENGINE/TRANSMISSION COSMETIC</b> | 7 | COSMETIC HEAVY - CHROME CORROSION, PAINT CHIPS                                    |     |
| <b>FAIRING/UPPER</b>                | 7 | COSMETIC HEAVY - TRIM SCRATCHES DING  |    |
| <b>FUEL TANK</b>                    | 7 | COSMETIC HEAVY - SCRATCHES, INSIDE NOT VERIFIED                                   |    |
| <b>SUSPENSION/FRONT</b>             | 7 | SEAL LEAK - STAINED, CORROSION  |    |
| <b>SUSPENSION/REAR</b>              | 7 | COSMETIC HEAVY  |   |
| <b>FAIRING/LEFT</b>                 | 7 | COSMETIC HEAVY - SCRATCHES  |  |
| <b>FAIRING/RIGHT</b>                | 5 | COSMETIC DAMAGE - CRACKED WITH PLASTIC CHIP MISSING                               |  |
| <b>FENDER/FRONT</b>                 | 5 | COSMETIC DAMAGE - DENTED, MODIFIED  |  |
| <b>FENDER/REAR</b>                  | 6 | MODIFIED PERMANENTLY - MODIFIED, HOLES AND TRIM ADDED                             |  |
| <b>LUGGAGE</b>                      | 6 | MODIFIED PERMANENTLY - CHIPS, SCRATCHES, MODIFIED HOLES DRILLED LIGHTING ADDED    |  |
| <b>REVERSE</b>                      | - | Not Rated   |  |
| <b>EXHAUST SYSTEM</b>               | 5 | COSMETIC DAMAGE - MODIFIED HOLES DRILLED CUT BAFFLES PUNCTURED, DENTED, SCRATCHES |  |
| <b>FINAL DRIVE</b>                  | 7 | HEAVY WEAR - SHAFT COVER CORROSION  |  |

|                                    |   |  |  |
|------------------------------------|---|--|--|
| <b>WHEEL(S)/FRONT</b>              | 7 | COSMETIC HEAVY - CORROSION   |     |
| <b>WHEEL(S)/REAR</b>               | 7 | COSMETIC HEAVY   |    |
| <b>CONTROLS/FOOT</b>               | 7 | HEAVY WEAR - CORROSION   |    |
| <b>CONTROLS/HAND</b>               | 7 | HEAVY WEAR - AFTERMARKET COMPONENTS, CORROSION, SCRATCHES                        |    |
| <b>FUEL TANK COVER/TRIM PIECES</b> | 7 | COSMETIC HEAVY - FADED, SCRATCHES  |    |
| <b>SHOCK(S)/REAR</b>               | 8 | COSMETIC LIGHT   |    |
| <b>STEERING</b>                    | 5 | COSMETIC DAMAGE - DENTED STEERING LOCK TAB                                       |    |
| <b>BRAKES/FRONT</b>                | 8 | LIGHT WEAR   |   |
| <b>BRAKES/REAR</b>                 | 8 | LIGHT WEAR   |   |
| <b>WINDSHIELD</b>                  | 7 | COSMETIC HEAVY - AFTERMARKET, SCRATCHES  |  |
| <b>ELECTRONICS</b>                 | 4 | INOP - SNAPPED CASSETTE DOOR   |  |
| <b>SIDE COVERS</b>                 | 0 | MISSING  |  |
| <b>TIRE/FRONT - CRUISER</b>        | 9 | 4/32 AND UP  |  |
| <b>TIRE/REAR - CRUISER</b>         | 2 | 2/32 OR LESS - SURFACE ABRASION  |  |
| <b>FOOT RESTS</b>                  | 4 | INCOMPLETE/PARTS MISSING - MODIFIED HOLES DRILLED LIGHTING INSTALLED, SCRATCHES, |  |

|                        |   |  |
|------------------------|---|--|
|                        |   | PASSENGER LEFT<br>REMOVED                            |
| <b>GAUGES/ODOMETER</b> | 9 | GOOD   |
| <b>GAUGES/OIL/VOLT</b> | - | Not Rated  |
| <b>LIGHTS</b>          | 5 | COSMETIC DAMAGE -<br>LENS CRACKED                    |
| <b>SEAT(S)</b>         | 5 | RIPPED/CRACKED                                       |
| <b>MIRRORS</b>         | 7 | COSMETIC HEAVY -<br>SCRATCHES,<br>HARDWARE CORROSION |
| <b>TURN SIGNALS</b>    | 5 | COSMETIC DAMAGE -<br>LENS CRACKED                    |
| <b>BATTERY</b>         | 4 | BATTERY<br>INOP/DAMAGED                              |
| <b>IGNITION SWITCH</b> | 9 | OPERATIONAL/HAS KEY                                  |
| <b>STAND</b>           | 5 | COSMETIC DAMAGE -<br>SNAPPED ASSIST TAB              |
| <b>STARTS/RUNS</b>     | 0 | NO - JUMP START<br>NEEDED                            |

